Tuesday, 12/6/2005 7:49:32 AM

Linda Lacelle User:

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number** : 25107

P.O. Number

: 10722

This Issue

: 12/6/2005

S.O. No. : HIP

Prsht Rev. First Issue Previous Run

Comment

: NC : Ma

: 24770

: LANDING GEAR Type

Part Number

Drawing Name

: D26547

Drawing Number : 7

D2654 REV E1

: 206 L WEB

Project Number

: N/A

Drawing Revision

: E1

Material **Due Date** : NA : 12/13/2005

Qty:

2 Um:

Each

Written By Checked & Approved By

Fixed typo, Changed procedure DM : Est Rev:D 99.02.04

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

D26007125

Qty



Comment: Qty.:

Pick:

1.0000 Each(s)/Unit Total:

2.0000 Each(s)

Part Number

Description Web

Batch 21/30

Extrusion 'I Beam' thick

D2600-7- 125

LANDING GEAR 1



2.0



Comment: LANDING GEAR RESOURCE 1

1-Cut D2600-7 to length as per Dwg D2654 f). a 35-12-06

2-Drill pilot holes in web using drill jig DT 8018-7 as perDwg D2654 A.M 05-/2-06

3-Using the uni-bit, open holes to finish size as per Dwg D2654 H.M. 05-12-06

4-Deburr holes and ends

A.m

03-12-06

3.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

4.0

HAND FINISHING1





Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1



H.M 05-12-06

Date: User: Tuesday, 12/6/2005 7:49:32 AM

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 206 L WEB

Job Number: 25107

Part Number: D26547

Job Number:



Seq. #:

Machine Or Operation:

Description:

5.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION

Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: L G

M 05-12-0

Job Completion



Document Control
Inspection level 21

Sur ostizior E



oslialos a

